


GM Application/Filter Interchange Update

Filter recommendations have been updated for some applications using the 57060. To comply with the change, the previous 57060 will be replaced with the WL10290 for select GM applications. The 57060 will remain an active part number and will still be offered for other non-select GM vehicles and applications.



57060




WL10290

Filter recommendations have been updated for some applications using the 57045. To comply with the change, the previous 57045 will be replaced with the WL10255 for GM applications. The 57045 will remain an active part number and will still be offered for Chrysler vehicles and applications.



57045



WL10255

Refer to WIX Electronic Catalog for updated filter fitment by application details.

As a reminder, it has always been, and remains our recommendation that the selection of a replacement filter be conducted using only the most current application information available. In today's cataloging, the electronic resources (i.e. Internet, interactive electronic) would be the most current application information available. For questions or more information, please contact your local WIX District Sales Manager or call Product Information at: US 1.800.949.6698, Mexico +52(844)8661-21-50, Canada 1-800-567-3703.